




Press On button

Factory setting - LBS

Press ENTER

PASSWORD (enter: 0 T 0 T)

Press ENTER F1

Press ENTER F1.1

Press ENTER F1.1.1

Press ENTER SCL

Press ENTER F1.1.2

Press ENTER NONE

Press ENTER F1.2

Press ENTER F1.2.1

Factory set LBS unit will appear on the screen

Press T to change the weighing unit to KGS

Press ENTER-SAVE-ENTER to set new unit KGS.